

ViziPrint®

Print Media

To ensure proper usage of ViziPrint® printable window film, please follow the recommendations listed below.

1. Use care when transporting the graphic and removing the release liner. The graphic should not be bent or distorted because the film will not flatten after being creased.
2. ViziPrint® will adhere to most smooth surfaces such as glass, aluminum, stainless steel, laminated surfaces, and plastics.
3. The surface where the graphic is to be applied must be clean and free of dust and dirt particles. These types of inclusions may cause small air pockets in the image.
4. Clean the surface with a suitable cleaner that will not leave streaks or residue on the surface. An adhesive or static roller can be used to remove any debris left behind during initial cleaning.
5. A low tack tape, such as painter's tape, can be used to position the graphic in the correct location and straight on the surface. Put a small piece of tape on the surface to help line up the top and side edges of the graphic.
6. Do not completely remove the release liner before starting the application process. Pull back a few inches of the release liner on the edge of the graphic and use a felt pad or felt-covered squeegee to apply it to the surface.
7. Position the graphic's exposed adhesive in the location that was marked beforehand with the tape. Apply the edge of the graphic to the surface. Work toward the opposite edge of the graphic, slowly pulling the release liner to gradually expose the adhesive and working from top to bottom as the graphic is installed.
8. Once the graphic is installed, carefully work out any air bubbles with a felt pad or felt-covered squeegee. The graphic can be pulled back and re-installed, if needed. It can also be repositioned up to ten (10) times. ViziPrint®'s adhesive sets up over time. After the first 24 hours, the graphic should be left in place until it is time to be removed and discarded.

IMPORTANT NOTE:

Please refer to the ViziPrint® TDS and MSDS for more information.

The technical information, recommendations and other statements contained in this document are based upon testing and experience Drytac believes to be reliable, but the accuracy and or completeness is not guaranteed. Drytac recommends a small test be performed to determine suitability beforehand. This document does not constitute a warranty of any kind.