


Professional M Series - Parts Diagram



Notes: -
 Parts marked with a (XX) are size dependent. Replace the XX with specific Machine Size (e.g. MT(XX) for M36 = MT36).
 Parts marked with an (X) vary in quantity dependent on the Machine Size (e.g. M107 for M12 - 4 feet, for M54 - 8 feet)
 M105 is not required for M12, M15 or M18.
 Parts are sold individually unless specified as a set.

MyBinding.com
 5500 NE Moore Court
 Hillsboro, OR 97124
 Toll Free: 1-800-944-4573
 Local: 503-640-5920

CSKIT Assembly

The CSKIT Assembly diagram shows the following components and their assembly:

- U2 (2)**: Two red screws.
- M133**: Small purple pin.
- M109 (2)**: Two green plates.